

Inspection Report - 2016 Manitou MT-X1840

24,596 hours | Location: United Arab Emirates | SKU: 1298037

Key Features & Condition	
Safety Certification Label	N/A
Axle Based 4WD	Yes
Electric Powered	N/A
Equipment Parts Manual	N/A
Electric Operating System	N/A
Horn Function	N/A
Travel Alarm	Yes
Operator's Manual	N/A
Emission Compliance Label	N/A
Diesel Powered	Yes
Operator Cabin Details	
Seat and Arm Support	Ok
control levers, Control swithes	Ok
Dashboard Screen, Gauges	Ok
Warning alarms message	Ok
Electrical System	Ok
Windows/ mirrors/ Wipers	Ok
Floor Mates	Ok
Engine	
Model	Perkins 1104D-44TA
Injection Type	Mechanical
Leaks	Minor coolant leak from wate-pump service hole
Oil Condition	Ok
Exhaust Smoke	Normal
Cooling System	Ok
Coolant	Ok
Sound	Ok
Blow By	Normal
Belts	Ok
Power	Ok
Exterior Condition & Visual Inspection	



Chassis	Ok
Sheet Metal	Ok
Side Doors	Ok
Boom Condition	Ok
Boom Linkage / Guides	Ok
Paintwork	Ok, repainted
Cooler Grill	Ok
Frame Condition	Ok
Outriggers	Ok
Batteries	Ok
Hydraulic System	
Hoses, Lines, Swivel	Ok
Pump And Valve Bloc	Ok
Steering Cylinder	Ok
Boom Lift Cylinder(s)	Ok
Telescopic Boom Cylinders	Ok
Carriage Tilt Cylinder	Ok
Frame Leveling Cylinders	Ok
Stabilizer Cylinders	Ok
Leaks	Minor oil leak from Hydraulic oil cooler fitting side
Drivetrain	
Transmission	Ok
Transfar Gear type	Manual
Transfer Case / Drop Box	Ok
Front / Rear Axle	Ok
Limited Functional Testing & Operation	
Drive Forward	Ok
Drive Reverse	Ok
Steering	Ok
Platform Function Controls	Ok
Boom Extension	Ok
Fork angle movment	Not functional
Wheel Bearing	Ok
Platform control	Ok
brake system	Ok
Lifting	Ok



Tires condition / Type / Size	
Axle 1 Right	80% BKT 16.9-24
Axle 1 Left	90% CEAT 16.9-24
Axle 2 Right	50% BKT 16.9-24
Axle 2 Left	50% BKT 16.9-24

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed

