

## Inspection report – 2018 Komatsu PC400LC-8R

Hours: 6711 | Location: Dubai, United Arab Emirates | SKU: 1308276

---

### Key Features & Condition

Safety Certification Label	N/A
Boom Hydraulic Check Valve	Yes
Adjustable Boom System	N/A
Automatic Lubrication System	Yes
Arm Hydraulic Check Valve	Yes
Diesel Particulate Filter	N/A
Hydraulic Hammer Lines	N/A
Grapple and Shear Hydraulic Lines	N/A
Diesel Exhaust Fluid System AddBlue	N/A
Stabilizer Blade Condition	N/A
Horn	Yes

---

### Operator Cabin Details

Seat and Arm Support	Ok
Cab Doors & covers	Ok
Control Levers, Control Stick	Ok
Windows and Mirrors	Ok, Left mirror are missing
Dashboard Screen, Gauges	Ok
Warning alarms message	Water meter sensor
Washer, Wipers	Ok
Air Conditioning & Heating System	Ok, Not cooling
Cab Floor Covering	Ok
Cab Structure, Gard	Ok
Electrical System	Ok

---

### Engine & Performance

Fuel Injection System	Electronic
Engine Model	SAA6D125E-5
Engine Cooling System	OK

---

#### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Engine Oil Check	OK
Cooling System	OK
Coolant	OK, Normal water
Exhaust System & Muffler	OK
Belts & Air/Oil Filters	OK
Smoke Check	Normal
Blow BY	Normal
Leaks & Seals	Ok

---

## Exterior Condition & Visual Inspection

Main Frame & Track Frame	Ok
Protective Covers & Sheets	Ok
Engine Hood	Ok
Side Access Doors	Ok
Steps and Handrails	Ok
Boom Condition	Ok
Bumpers & Catwalk Condition	Ok
Arm Condition	Ok
Lights	Ok, One light need bulb
Battery Check	Ok
Cabin Compartments	Ok
Exterior Paint Condition	Ok, Some parts repainted

---

## Hydraulic System

Hydraulic Leaks	Ok
Boom Hydraulic Jack	Ok
Hydraulic Pump & Valve Block	Ok
Bucket Hydraulic Jack	Ok
Arm Hydraulic Jack	Ok

---

## Performance analysis

Boom Pins Condition	Ok
Excavator self- Drift Test	Ok
Arm Pins Condition	Ok, Minor loose

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)



Hydraulic Pump Noise Check	Ok
Bucket Pins Condition	Ok, Minor loose
Slewing Ring Bearing Movement Check	Ok, Minor loose
Swing Drive and Brake Test	Ok
Drive force Test	Ok

---

## Attachments

Attachments model	bucket
Size	W1750 \H1750 \D115
Status	OK
Coupler Status	Minor welded
Second Attachments model	N/A
Size	N/A
Status	N/A

---

## Undercarriage

Bushings	60%
Track Shoes	80%
Idlers	60%
Shoe Width in mm:	800mm
Track Pitch in mm:	60mm
Carrier Rollers	60%
Track Rollers	60%
Track Links	70%
Sprocket Segments	70%

---

No guarantees made as to actual hours/miles/kilometers; the inspection report reflects what can be visually observed.

---

### PANDE Auctions LLC

Dubai, PO Box: 71530, Dubai, United Arab Emirates

Tel: +971 4 5808020

[www.PlantAndEquipment.com](http://www.PlantAndEquipment.com)

